TO: Patrick Nejand, Project Manager

Ken Mass, Project Manager

United States Army Corps of Engineers (USACE)

FROM: Shannon Lloyd, Project Manager

Los Alamos Technical Associates, Inc. (LATA)

SUBJECT: November 2014 Inspection Report for the former Cornell Dubilier Electronics (CDE)

Superfund Site, South Plainfield, New Jersey

LATA Project # 11266

Contract # W912DQ-09-D-3003,

Task Order # 0011

DATE: November 19, 2014

CURRENT ACTIVITIES

LATA's technician visited the Cornell Dubilier Electronics (CDE) Superfund Site for the regularly scheduled inspection visit on November 13, 2014 to perform the routine inspection of the facilities.

Work performed during the visit included; picked up trash from the fence line, inspected the catch basin and drainage basin system, inspected the perimeter fence, gates, etc., pulled woody vegetation from accessible areas of the drainage basin, download the data from the basin dataloggers and performed a walking inspection of the asphalt cap areas. Copies of the inspection forms are attached to this report.

Approximately one bag of trash (paper, plastic bottles, etc.) was picked up from around the fence line in various areas. The trash was disposed of in the local technicians office dumpster.

MANPOWER REPORTING

Date	LATA Labor
November 13, 2014	3 hrs.

OUTSTANDING ISSUES/RESOLUTIONS

LATA submitted the DRAFT Accident Prevention Plan for review by USACE on July 3, 2014.

PLANS FOR NEXT MONTH

Plans for the December 2014 visit includes inspection and general housekeeping activities and downloading the drainage basin level datalogger. A snow removal has been placed under contract to remove snow from the sidewalk paralleling the Hamilton Boulevard when snowfall totals are greater than two inches. This removal will be made on an as needed basis.

Site Inspection Forms and Photo Log

Inspection being Conducted		X		Monthly				
Quarterly		_Annually			_After 1" or Grea	nter Rainfall		
Inspection Date:	11/13/2014	l .		_	Weather	Overcast, 4	.0s	
Inspectors Name	Sunil Samar	00						
Basin Inspection:						.,		21/2
Catch Basins (23 Structures) 1. Are catch basins properly draining?						Yes	No .	N/A
2. Are the catch basin3. Has vegetation been						X		
4. Are there any signs If yes, which catch ba (Refer to Record Draw	s of damage or sin(s)?	deterioratio	n of catch				X	
Stormwater Detention	on Basin and S	urface Sand	Filter:					
5. Does the basin hav	· ·	anding water	?				X	
6. What is the water Approximately how n How many inches of	nany hours wa	(~ 6 inc s the last rai	•					
7. Does the bottom appear relatively flat? No sand has washed away?				X				
8. Are concentrated f	9			rected into t	he basin?	$-\Box$	X	
9. Is there any damag								
10. Has vegetation been removed from the basin areas? Woody vegetation was removed by pulling/cutting at gr				utting at gro	und level.	<u> X</u>		

Inlet and Outlet Structures: 11. Are the five inlet and outlet structures draining properly?	X		
12. Is there any standing water? If yes, describe where		X	
13. Are the inlets clear of trash, sediment and debris?	X		
14. Are the outlets (standpipes, 3" Orifice, secondary outlet and emergency spillway) clear of trash, sediment, and debris?	X		
15. are there any signs of damage or deterioration of inlet/outlet structures? If yes, describe where		X	
16. Has vegetation been removed from inlet and outlets?			Χ
Additional descriptions of where repairs or maintenance is needed:			
			-
Inspector's Signature Secret Auruardo			

Inspector's Signature

Inspection Date:	11/13/2014	Weather	Overcast, 4	.0s	
Inspectors Name	Sunil Samaroo				
		"Tree Grove" Inspection			
			Yes	No	N/A
1. Is there any tree dan If yes, describe:	mage from storms?			X	
2. Is there an accumula	ation of tree debris?			X	
If yes, describe:					
3. Do any trees appear	r infested?				Χ
If yes, describe:					
4. Do any trees appear	r malnourished?				Χ
If yes, describe:	rly Seasonal Maintenance Pe	rformad2			
Date of previous main	·	Hormeu :			
•	of the Operation & Maintena	ance Manual)			
•	Arborist Inspection perform	•			Х
Date of previous inspe					
	of the Operation & Maintena	ance Manual)			
Additional description	s of where repairs or mainter	nance is needed:			
Tree buffe	r being maintained "as is" by	direction of USACE and EPA.			
Inspector's Signature	Lunil Aur	mardo			

Inspection Date:	11/13/2014	Weather	Overcast, 40s	
Inspectors Name	Sunil Samaroo			
Debris, Trash, Vege Comments	tation and Sediment Removal and Inspo	ections		
Remove	d trash from perimeter fence.			
One bag	of trash, 2/3 filled, disposed of at URS	dumpster.		
Over all,	the site remains in good condition.			
General Housekeepi	ing			
Comments	S			
Spot spr	ayed weeds in asphalt area with Round	l Up.		
	has minor cracking predominantly at se			
Fencing and Gates				
Comments				
GOOD				
-				
Trash and Debris				
Comments				
(See abo	ove)			
Snow Removal				
Comments				
N/A				

Pavement Inspection (Part of Annual Inspection)

	Yes	No	N/A
1. Is there any standing water?			X
If yes, describe where			
2. Are there any signs of cracking?	Χ		
If so, note location and maintenance effort below.			
3. Are there any signs of disintegration?			Χ
If so, note location and maintenance effort below.			
4. Are there any sins of distortion?			Χ
If so, note location and maintenance effort below.			
5. Has all vegetation been removed?	Χ		
If applicable, note location of vegetation below			
6. Has usage of the site increase to a point that warrants a Pavement Condition			Χ
Index (PCI) Survey?			
7. Have any Critical Preventative Maintenance (CPM) Pavement Treatments			Χ
been applied?			
When was date of the last CPM treatment?			
(Refer to Section 2.2.3 of the Operations & Maintenance Manual)			
Additional descriptions of where repairs or maintenance is needed:			
Cracks in asphalt developing in the area of the water tower, previously observed	d		
			-
Inspector's Signature			

Basin Drainage Rate Ins (completed twice a yea	pection: r after a design rainfall event)
Date:	
Design Rainfall Event In Requirements: 1.25" of	
Start:	
Stop: Inches of Rainfall:	
inches of Rainfall.	

Inspection Data

Start inspections 16 hours after design rain event Perform subsequent inspection every 2 hours until height of water drops below the to of the aggregate in the middle basin

Inspection Run #	Target time from Event (hrs)	Actual Time	Water Height (ft)
1	16		
2	18		
3	20		
4	22		
5	24		
6	26		
7	28		
8	30		
9	32		
10	34		

Note approximate time water was drained below top of sand bed and compared to the normal	
drain time of 21 hrs.	

Increator's Signature

Inspector's Signature

11-13-2014 Cornell-Dubilier Electronics

Site Inspection photos

Fence drive by inspection photos









Additional site photos





